



Technical Bulletin

March 24, 2008

BROADCAST ELECTRONICS CUSTOMER SERVICE

Recipients of this Technical Update receive notices from BE Customer Service on product updates and other information for users of BE equipment.

BE SUPPORT

Radio Transmitters & RF Products

Tel: 217.224.9617

rfservice@bdcast.com

AM 2.5E, AM 5E, AND AM 6A SAFETY INTERLOCK SWITCH RECALL NOTIFICATION



Broadcast Electronics is announcing a recall on the On/Off Safety Interlock switch used in the AM 2.5E, AM 5E, and AM 6A transmitters shipped from the factory between the dates of January 19, 2007 to March 7, 2008.

A malfunction in a plastic part used in the interlock has been discovered by the manufacturer. This malfunction could cause a danger to life during installation and maintenance work. The malfunction may cause one of the 3 poles to remain energized, even when the switch is turned to the OFF position.

The manufacturer's original safety notice is available from the Broadcast Electronics Customer Service website here:

[Original Manufacturer's Safety Notice](#)

Please note that this will also affect any parts order shipment for p/n 341-0061 (Safety Interlock switch, 60Amp) during January 19, 2007 to March 7, 2008.

All units shipped from Broadcast Electronics after the March 7, 2008 date will already include the improved safety interlock switch.

Broadcast Electronics will make a replacement interlock available free of charge. Contact the RF Service department by phone at 217.224.9617 or e-mail rfservice@bdcast.com and request the 341-0061 Safety Interlock.

Thank you for choosing Broadcast Electronics!

www.bdcast.com

Broadcast Electronics, Inc. [Legal notices](#)